



Coordinate Measuring Machine Training - Utilizing PC-DMIS®

- Software overview
- Probing:
 - Build a probe
 - Add angles
 - Define calibration sphere
 - Calibrate a probe
- Measured features:
 - Point
 - Line
 - Circle
 - Plane
 - Cylinder
 - Cone
- Alignments:
 - Plane, line, point
 - Plane, line, circle
 - Plane, circle, circle
 - Cylinder, line, point
 - Cylinder, point
 - Translate
 - Recall
- Construct:
 - Point
 - Line
 - Circle
- DCC:
 - Mode
 - Clear plane
 - Moves
- Auto features:
 - Point
 - Line
 - Circle
 - Plane
 - Cylinder

- Cone
- Dimension:
 - Location
 - TP
 - Distance
 - Angle
 - Roundness
 - Flatness
 - Perpendicular
 - Parallelism
- Comments:
 - Operator
 - Report
- Edit:
 - Nominal's
 - Tolerance
- Report:
 - Print
 - Save to file